



RUBBER INTERTRADE CO., LTD.


Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

List of New Products

MAZDA

D21MZ02F1 NEW CN155484AA, CN1Z5484B, DN21 34 156A MAZDA2 (2012) DE, (4D, 5D SPORT), ECOSPORT Stabilizer Shaft Rubber (FR)	 B : 8 / C : 192 pcs.	
--	---	--

TOYOTA

T09AH20LZ NEW 12372-28390-IN ALPHARD ANH20, ESTIMA ACR50 Insulator Engine (LH)	 B : 1 / C : 8 pcs.	T13CR19F NEW 48609-06410 CAMRY ASV71 (2019) Shock Absorber Mounting (FR)	 B : 1 / C : 20 pcs.
T14AG30F1 NEW 48331-58010 ALPHARD AGH30 (2015) Shock Absorber Bumper (FR)	 B : 6 / C : 72 pcs.	T14AN10F1 NEW 48331-28040 ALPHARD ANH10 (2002-2007), ESTIMA ACR30, ACR40 (2000-2006) Shock Absorber Bumper (LH,RH)	 B : 6 / C : 72 pcs.
T14F65F1 NEW 48331-BZ110 AVANZA F651 Shock Absorber Bumper (FR)	 B : 6 / C : 72 pcs.	T25AH30800 NEW 48780-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)	 B : 2 / C : 24 pcs.
T25AH30200 NEW 48720-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)	 B : 6 / C : 108 pcs.	T25AH30400 NEW 48740-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)	 B : 6 / C : 108 pcs.
T26F60R NEW 45516-BZ140 AVANZA F601 Grommet Steering Bush (RH)	 B : 10 / C : 180 pcs.	T26GD30E0 NEW 48530-80A06-0, 48537-26010 GDH300 Shock Absorber Bush (RE)	 B : 8 / C : 144 pcs.
T27FT15E NEW 48830-0K010 FORTUNER (2015) Link Assy (RE)	 B : 2 / C : 54 pcs.	T27YR19F0 NEW 48820-WB002 YARIS DADW1, DAEA1 (2016-2019), YARIS R (2016), YARIS IA (2017), SCION IA (2016) Link Assy (FR, LH, RH)	 B : 2 / C : 40 pcs.



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

TOYOTA

T27KD12FL NEW 48810-60040 PRADO (2009) GRJ121, KDJ121, TRJ150 Link Assy (FR, LH)  B : 2 / C : 54 pcs.	T27KD12FR NEW 48820-60050 PRADO (2009) GRJ121, KDJ121, TRJ150 Link Assy (FR, RH)  B : 2 / C : 54 pcs.
T28IN15E NEW 48341-0K150 INNOVA GUN143 Bumper Bound (RE)  B : 2 / C : 24 pcs.	

MITSUBISHI

M26XP18EW NEW 4162A409-0 XPANDER (2018) NC1W Shock Absorber Bush (RE)  B : 6 / C : 108 pcs.	
---	--

NISSAN

N19T32EP NEW 55034-EN101 X-TRAIL T31, T32 (2013) Coil Spring Rubber (RE, UPPER)  B : 4 / C : 64 pcs.	N27Y61E0 NEW 56260-VC300 PATROL Y61 (1997-2013) Link Assy (RE)  B : 2 / C : 54 pcs.
N25Y62EP NEW 55045-1LB0A, 55501-1LB0A-0 PATROL Y62 Suspension Bush (UP RE LH,RH)  B : 4 / C : 72 pcs.	N25Y62EW NEW 551A0-1LB0B-0 PATROL Y62 Suspension Bush (LOW RE LH,RH)  B : 4 / C : 72 pcs.

HONDA

O14305E0 NEW 52610-SEL-T22-3 CITY (03) G2, (06) ZX, (08) G3, JAZZ (04) GD, (09) GE, BRIO, AMAZE (11), BR-V (16) Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	O14515E1 NEW 52722-T8N-T01 HR-V (2015) Shock Dust Cover (RE, INNER)  B : 2 / C : 12 pcs.
--	---